VISIBLE EMISSION NOTATIONS				
	<i>+</i> ~			
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	Time:			
Unit Visible Emission From Shaker	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
	Nov	Nonelitharitti-		
Visible Emission From Discharge Conveyor System	Na	gggggggggggggggggggggggggggggggggggggg		i i

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)





VISIBLE EMISSION NOTATIONS

		_		
Inspector: Seremy Hardi	3			
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	D Time:	icean		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	nomal			
Visible Emission From Discharge Conveyor System	aronnal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Conveyor System	Visible Emission From Shaker	Cnin	VISIBLE EMISSION NOTATIONS Inspector: Chewa Scwced Date of Inspection: R J 3 / 1 5 Shift: 1st Shift or 2nd Shift Visu
WORME (NORmal	Inspection NORMAL Or ABNORMAL	Time: 5/5 AM
			Comments

- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal. Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- characteristics of normal visible emissions for that specific process. or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit. If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Chema Sa	ncedo				
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	530 AM			
di Unit.	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comme	ents	
Visible Emission From Shaker	No Paren!				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Paul La	rl				
Date of Inspection:	18				
Shift: 1st Shift or 2nd Shift	Time:	5:03 AW			
Unit 1	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Con	nments	
Visible Emission From Shaker	Aprer	stoalce!			
Visible Emission From Discharge Conveyor System	, Vol	V			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector:	(oland]		
Date of Inspection: 61579	Epi			÷	
Shift: 1st Shift or 2nd Shift	: Time:	5:00pm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Commen		
Visible Emission From Shaker	Norm				
Visible Emission From Discharge Conveyor System	Norm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Paul Carl		·			
Date of Inspection: 8-6-15					
Shift: 1st Shift or 2nd Shift	Time:	5:00 AM		·	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Com	ments	
Visible Emission From Shaker	ABnor				
Visible Emission From Discharge Conveyor System	Nov				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE FINITZZION NOTATIONZ					
Inspector:	total				
Date of Inspection: 816 (2	915				
Shift: (1st Shift) or 2nd Shift	Time:	5.00pm			
Unit.	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		(Con	nments	
Visible Emission From Shaker	Worm				
Visible Emission From Discharge					
Conveyor System	Norm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector:	1.				
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	\$7.00 MW			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Commer	nts	
Visible Emission From Shaker	Morar				
Visible Emission From Discharge Conveyor System	Not				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)


VISIBLE EMISSION NOTATIONS					
Inspector:	10/al				
Date of Inspection: 8/7/2	2012				
Shift: 1st Shift or 2nd Shift	Time:	S:00p-			
Unit.	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Com	nments	
Visible Emission From Shaker	Norm				
Visible Emission From Discharge Conveyor System	Norm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



VISIBLE EMISSION NOTATIONS			_		
Inspector: Ted Cnx	ot ~~				
Date of Inspection: 8/8/15					•
Shift: 1st Shift or 2nd Shift	Time:	Spm			
Unit Visible Emission From Shaker	Misual Inspection Normal Por ABNORWAL		Con	nuan erenges	
Visible Emission From Discharge Conveyor System	N		Tadifference places processed and comment principles of the comment of the commen		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



AISIBLE FIMISSION MOTATIONS						
Inspector: 1 ed Caro	ta					
Date of Inspection: 8/9/15					•	
Shift: 1st Shift or 2nd Shift	: Time:	5PM				
Unite	Visval		Co	nimenes		
	<u>Moramal</u>					
	oj <u>ABNORIMVAL</u>					
Visible Emission From Shaker	Nos	Contraction out and supplied to a contraction out				
Visible Emission From Discharge						
Conveyor System	Na					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Paul Lark					
Date of Inspection: 8 10-13	<u> </u>				
Shift: 1st Shift or 2nd Shift	Time:	5:00 Av			
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		CÓ	mments	
Visible Emission From Shaker	ABrer				
Visible Emission From Discharge Conveyor System	NOC				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS	W. C.		_		
Inspector: Duben NW	landit				
Date of Inspection: 8/10/3	015				
Shift: 1st Shift or 2nd Shift	Time:	5:00pm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Li.Cor	nments	
Visible Emission From Shaker	Norm				
Visible Emission From Discharge Conveyor System	Norm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Paul Lorle	military (m. 1940)				
Date of Inspection: 8-11-15					
Shift: 1st Shift or 2nd Shift	Time:	5:00 bm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comment	CS	
Visible Emission From Shaker	ABOX	CPDar	= d	,	
Visible Emission From Discharge					
Conveyor System	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector:	Mohand	Name and the second sec]		
Date of Inspection:	13				•
Shift: 1st Shift or 2nd Shift	Time:	5:00pm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comn	ments	
Visible Emission From Shaker	Normal				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: (1st Shift) Time: Unit Visual Comments Inspection NORMAL or **ABNORMAL** Visible Emission From Shaker Visible Emission From Discharge Conveyor System

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: 1st Shift Time: Spm Unit Visual Comments Inspection NORMAL or ABNORMAL Visible Emission From Shaker Non Visible Emission From Discharge Nor Conveyor System

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Jamian Sali	nas Dr				
Date of Inspection:					•
Shift: 1st Shift or 2nd Shift	Time:	5pm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Con	nments	
Visible Emission From Shaker	Nov	estinguishing.			
Visible Emission From Discharge Conveyor System	Nov	Same			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: Paul Lan				
Date of Inspection: 8-15-15				
Shift: 1st Shift or 2nd Shift	t Time:	5:00 AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments :	
Visible Emission From Shaker	AB cor			
Visible Emission From Discharge				
Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AIZIBLE EMISSION NOTATIONS						
Inspector:	Moland					
Date of Inspection:	8015					
Shift: 1st Shift or 2nd Shift	: Time:	5:00pm				
Unit	Visual		Co	mments		14.7
	Inspection					
	<u>NORMAL</u>			10 (10 m) (10 m) (10 m)	Company (Sept.)	
	or			100		
	<u>ABNORMAL</u>					
Visible Emission From Shaker	Domal					
Visible Emission From Discharge					· · · · · · · · · · · · · · · · · · ·	
Conveyor System	NO WELL	2				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Paul Larl					
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm			
Unit	Visual Inspection		Comr	ments.	
	<u>NORMAL</u>				
	or ABNORMAL				
Visible Emission From Shaker	ABror	Copaire			,
Visible Emission From Discharge	2 (V V			
Conveyor System	1/01				

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Revised 5/1/2015

VISIBLE EMISSION NOTATIONS	e-		-		
Inspector:	Noland				
Date of Inspection:	30/5				
Shift: 1st Shift or 2nd Shift	t Time:	6:00pm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Commer	nts.	
Visible Emission From Shaker	Nomme				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE FIMISSION NOTATIONS			<u></u>	
Inspector: Damian Sal	inas Ji			
Date of Inspection: $9-17-1$	5			
Shift: 1st Shift or 2nd Shift	: Time:	5pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		. Comments.	
Visible Emission From Shaker	No			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Wamian S	alinas Jr				6
Date of Inspection: \$-18-15	-				
Shift: 1st Shift or 2nd Shift	t Time:	5pm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comp	ments	
Visible Emission From Shaker	Nor	gggamainteganiste			
Visible Emission From Discharge Conveyor System	Nor	*Allerentine			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE LIVISSION NOTATIONS			<u></u>		
Inspector: Lime A GORG	'a				
Date of Inspection: 8/19/15					
Shift: 1st Shift or 2nd Shift	Time:	5AM			
Unit	Visual Inspection 4. NORMAL SOI ABNORMAL			mments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Non				

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VICIDIE ENVICCIONI NIOTATIONIC

AISIDEE EIMISSION NOTATIONS					
Inspector: Ree M	ded				
Date of Inspection: 81 191	2015				· ·
Shift: 1st Shift or 2nd Shift	Time:	5:00m			
Unit tr	Visuali Inspection NORMAL Tor		on we consider the constant of	nmenus.	
Visible Emission From Shaker	Normal				·
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE FIMIZZION NOTATIONS					
Inspector: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	5.60 pm			
Unit	Visual Inspection		en Con		
	<u>NORMAL</u> o/ ABNORMAL				
Visible Emission From Shaker	ABror	Verane		n bereit er	s consept processors and a consequence of the conse
Visible Emission From Discharge					
Conveyor System	101		•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: Puber	Moland			
Date of Inspection: 8 20 2	015			•
Shift: 1st Shift or 2nd Shift	: Time:	5:00pm		
Unit	Visual 22/4 Inspection		nimenis	
	<u>NORMAL</u> Of			
	ABNORMAL			
Visible Emission From Shaker	Normal			
Visible Emission From Discharge	0 7000 0 - 1			
Conveyor System	NOUTHOLL			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)





VISIBLE EMISSION NOTATIONS			-1		
Inspector: Paul Lail					
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	ے :Time	S: 00 AM			
.Umit	Wisual Inspection <u>Morawal</u> or		Co	emmenus	
Visible Emission From Shaker	ABNORMAL AY				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)






Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Visible Emission From Discharge

Conveyor System





VISIBLE EMISSION NOTATIONS			_		
Inspector: Reben 1	Udal				
Date of Inspection: 8 08 1	3015				
Shift: (1st Shift or 2nd Shift	Time:	5:00pm			
Unit	Misual Inspection NormAL or ABNORMAL		Com	lments	
Visible Emission From Shaker	Normal	The tree of the control of the contr			
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)





AISIDEE EIAIISSION MOTATIONS	<u> </u>		_		
Inspector: Ruban L	blamol I	PMODE de alleman			
Date of Inspection: 8 38 8	OIS				•
Shift: 1st Shift or 2nd Shift	Time:	5:00pm			
Unit _	Visual Inspection		Con	nimen4	
	<u>invatanala.</u> (0) <u>ABNIORIMIAL</u>				
Visible Emission From Shaker	Sormal				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



VISIBLE EMISSION NOTATIONS					
Inspector:					
Date of Inspection:	<u> </u>				
Shift: 1st Shift or 2nd Shift	Time:	5100			
J ak.	Misual Imsperdign <u>Nicrimal</u> Or ABNORIMAL		Go	inimenus	
Visible Emission From Shaker	AB				
Visible Emission From D ischarge Conveyor System	nov				


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)





VISIBLE EMISSION NOTATIONS,					
Inspector:					
Date of Inspection: 8/25					
Shift: 1st Shift or 2nd Shift	Time:	50M		·	
Umit.	Msval Mispedion Morimal or			ammenus	
Visible Emission From Shaker	ABNORMAL (*)				
Visible Emission From Discharge Conveyor System	No-	о-46 біду міністі Мастий Пайтый Адрій ідрабу сетьый Перету на	ten flagt flage frage frage flag på likelige til det flagt flagt flagt flagt flagt flagt flagt flagt flagt flag		


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



VISIBLE EMISSION NOTATIONS			 .		
Inspector:	1-				
Date of Inspection: 8/26/15					•
Shift: 1st Shift or 2nd Shift	Time:	5PM			
Unit	Wishell linspection		Co	វិភាវភាមិស៊ីមិន	
	<u>Mormal</u>				
	ABNORMAL				
Visible Emission From Shaker	N./	er de la faction de la companya del la companya de	Section with the graph of the section of the sectio		
Visible Emission From Discharge	,				
Conveyor System	No	yer pyffing falling fan gangaein fan fan gangaein fan fan fan gangaein fan fan fan fan fan fan fan fan fan fa	AND CONTRACT OF CONTRACTOR AND CONTR		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)





VISIBLE EMISSION NOTATIONS					
Inspector:	'anoton'				
Date of Inspection: 8/27//	5-17				•
Shift: (1st)Shift or 2nd Shift	Time:	5 Pm			
). Unite	Misual Inspection <u>Normal</u> Of ABNORMAL		Con	niments	
Visible Emission From Shaker	Nov-	«Чтор» для оббагать поторые наводаться пользорацию домущеную на меняте тет отно-	aphillosophicophilippeles (dendamiconic		
Visible Emission From Discharge Conveyor System	Nov		ottopia kanangan ngangan situ pangangan na maran		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



VISIBLE EMISSION NOTATIONS			~-		
Inspector: Ted Const	Pag				
Date of Inspection:	autoria.				
Shift: 1st Shift or 2nd Shift	Time:	5 PM			
Visible Emission From Shaker	Maval Imspection Normal or ABNORMAL		ec	novaenus	
VISIDIE EITHSTOTT FOUT STICKET	Nor	et y part from the petition of the period of the petition of t	MONETON CONTRACTOR CON		
Visible Emission From Discharge Conveyor System	No	entite habita sa principales at transport til til sakkel spatter som en til til sakkel spatter som en til til s	Mention of the contract of the		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



VISIBLE EMISSION NOTATIONS	C				
Inspector:					
Date of Inspection: 8/29//	5]		
Shift: (1st shift or 2nd Shift	Time:	5 g n		·	
Whit	Misual Inspection MORMAL or ABNORMAL			omments	
Visible Emission From Shaker	Nor	. Quantifica mente parametro de contractivo de cont	salligijiisaligideksijijaksijijajikajijimpi kilmalakkymeniyyen syyy		
Visible Emission From Discharge Conveyor System	N.	ye en Frairm-noon haal ole op en oor met alle gelde en oor ook op en skrijke die geskep old naar he was	lasting makipat ng 1946 at ng minambant pantauring na manambant pantauring na manambant pantauring na manambant		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



AISIBLE FIMISSION NOTATIONS			_		
Inspector:	1 1				
Date of Inspection: 8/30//	5				•
Shift: 1st Shift or 2nd Shift	: Time:	5007			
Waii	Misual Inspection I <u>MORMAL</u> OF <u>ABNORMAL</u>		(Co)	nimenus	
Visible Emission From Shaker	Nov	***Depoint of a season from the first of the	306.000-9 Good May on State St		
Visible Emission From Discharge					
Conveyor System	Nor	general companies of the contraction of the contrac	tiga garinaming kentrantit no gali fina pilah kelah kelah kentranti kentranti kentranti kentranti kentranti ke		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)







VISIBLE EMISSION NOTATIONS			_			
Inspector:	3					
Date of Inspection:	15				•	
Shift: 1st Shift or 2nd Shift	t Time:	50m				
	Misual Inspesition I <u>nformat</u> of <u>Abnorimat</u>		TO STATE OF THE ST	Comments		
Visible Emission From Shaker	No	- The state of the	Tavid 6.4 kg/g/(20)wwgohalari			
Visible Emission From Discharge Conveyor System	N		COMMUNICATION AND AND AND AND AND AND AND AND AND AN			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)